

**MADDOCK MUNI** (6D3) 1 N UTC-6(-5DT) N47°58.67' W99°31.62'

TWIN CITIES

1600 FUEL 100LL NOTAM FILE GFK

RWY 12-30: 3200X100 (TURF)

RWY 12: Road.

RWY 30: Road.

**AIRPORT REMARKS:** Attended on call. For attendant call 701-438-2694. Deer and birds on or in/ovf arpt. No snow removal, confirm arpt condition during winter months. Midfield E/W asph twy open to west side apron and hangar.

COMMUNICATIONS: CTAF 122.9

**MANDAN MUNI** (Y19) 4 S UTC-6(-5DT) N46°46.08' W100°53.66'

TWIN CITIES

1944 B S4 FUEL 100LL NOTAM FILE GFK

L-14F

RWY 13-31: H4399X75 (ASPH-AFSC) S-12.5 MIRL

IAP

RWY 13: REIL. VASI(V2L)—GA 2.5° TCH 40'. Trees.

RWY 31: REIL. VASI(V2L)—GA 3.0° TCH 40'. P-line.

RWY 04-22: 2921X140 (TURF) MIRL 0.7% up NE

RWY 04: Road.

**AIRPORT REMARKS:** Attended Mon-Fri 1400-0200Z†, Sat-Sun on call.

For fuel 24 hour self svc with credit card or call 701-663-0669.

Confirm snow removal after major winter storms with arpt

manager 701-663-0669/3690 or 701-391-1394. Rwy 04-22

and Rwy 13-31 intersection transition across Rwy 04-22 uneven

and be alert for high speed acft movements. 200' tower located

9500' NW of Rwy 13-31. 120' tower located 5000' SW of Rwy

04-22. MIRL Rwy 13-31 and Rwy 04-22 preset on med to

increase ints to ACTIVE—CTAF. ACTIVATE VASI Rwy 13 and Rwy 31

and REIL Rwy 13 and Rwy 31—CTAF.

**WEATHER DATA SOURCES:** AWOS-3 118.225 (701) 663-0271.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ BISMARCK APP/DEP CON 124.2 (1200-0600Z‡)


Ⓡ MINNEAPOLIS CENTER APP/DEP CON 125.6 (0600-1200Z‡)

RADIO AIDS TO NAVIGATION: NOTAM FILE BIS.

BISMARCK (L) VORW/DME 116.5 BIS Chan 112 N46°45.71' W100°39.92' 260° 9.5 NM to fld. 1841/12E.

HIWAS.

ASR (1200-0600Z‡)

**MAYVILLE MUNI** (D56) 1 S UTC-6(-5DT) N47°28.50' W97°20.02'

TWIN CITIES

975 B NOTAM FILE GFK

L-14G

RWY 17-35: H3200X56 (ASPH) S-4 LIRL

RWY 17: Road.

RWY 35: P-line.

**AIRPORT REMARKS:** Attended Apr-Oct 1300-0100Z†, Nov-Mar/Mon-Fri on call. For attendant call arpt manager at 701-786-2065. Migratory waterfowl on and in/ovf arpt. Irregular snow removal confirm with city maintenance, call 701-786-2166. Arpt has numerous flight training ops daily from Grand Forks Intl arpt. Rwy 17 turn around caution broken asphalt ruts. Rwy 17-35 west side of rwy lgts OTS indef. Rwy 17-35 3050' lgtd ngt time due to Rwy 17 thld lights 150' inbound of thld. ACTIVATE LIRL Rwy 17-35—CATF.

COMMUNICATIONS: CTAF/UNICOM 122.8

RADIO AIDS TO NAVIGATION: NOTAM FILE GFK.

GRAND FORKS (H) VORW/DME 114.3 GFK Chan 90 N47°57.29' W97°11.12' 183° 29.4 NM to fld. 841/9E.

HIWAS.

**McCLUSKY MUNI** (7G2) 2 SW UTC-6(-5DT) N47°27.73' W100°29.24'

TWIN CITIES

1900 B NOTAM FILE GFK

RWY 13-31: 3100X80 (TURF) LIRL

RWY 31: Trail.

**AIRPORT REMARKS:** Unattended. Confirm irregular snow removal and winter conditions with arpt manager prior to use; snow removal emerg only; call 701-363-2265/2244/2708. Rwy 13-31 has numerous grass clumps. Twy lgtd on north side only. Rotating bcn OTS indef. ACTIVATE LIRL Rwy 13-31—CTAF.

COMMUNICATIONS: CTAF 122.9